


Note: The drawing sizes may be different from the indicated sizes, so don't make actual measurement of the drawing shape.


| | |
|----------------------|----------------------|
| Plant section | Japan |
| | Foreign countries |
| | () |
| | () |
| | Not yet decided |
| | () |
| | () |
| Number of mold drive | |
| Weight | |
| 20 | |
| 19 | |
| 18 | |
| 17 | Approval |
| 16 | |
| 15 | Drawing inspection |
| 14 | |
| 13 | |
| 12 | |
| 11 | |
| 10 | |
| 9 | Designing |
| 8 | |
| 7 | |
| 6 | Working-out drawing |
| 5 | |
| 4 | Fitting of drawing |
| 3 | Our used early model |
| 2 | Copping of drawing |
| 1 | Temporality name |



| | | | | |
|--------------------|-----------|------------|------------------|--------|
| Material dimension | © | () | 6002B | (5/10) |
| Processing | © | () | SP. CONTROLLER | () |
| Size tolerance | Ⓑ | () | | |
| 1000 ± | | | | |
| 300-1000 ± | Ⓐ | () | | |
| 100-300 ± | Symbol | Date | Content revision | |
| 100 ± | Part name | Parts cord | | |
| Scale | Quantity | Unit mm | | |
| Unit mm | Scale | Unit mm | | |


Note: The drawing area may be different from the indicated sizes, so don't make actual measurement of the drawing shape.

| | |
|----------------------|----------------------|
| Plant section | Japan |
| Foreign countries | () |
| () | () |
| Not yet decided | () |
| Number of mold drive | |
| Weight | |
| 20 | |
| 19 | |
| 18 | |
| 17 | Approval |
| 16 | |
| 15 | |
| 14 | Drawing inspection |
| 13 | |
| 12 | |
| 11 | |
| 10 | |
| 9 | |
| 8 | Designing |
| 7 | |
| 6 | |
| 5 | Working out drawing |
| 4 | Filing of drawing |
| 3 | Our used early model |
| 2 | Copying of drawing |
| 1 | Temporarily name |



| | | | | |
|--------------------|---|-----|--------|--------|
| Material dimension | © | () | 6002B | (6/10) |
| Processing | ⓑ | () | SP RAM | () |
| Size tolerance | Ⓐ | () | | () |
| 1000 ± | | | | |
| 300-1000 ± | | | | |
| 100-300 ± | | | | |
| 100 ± | | | | |
| Scale | | | | |
| Quantity | | | | |
| Unit mm | | | | |

The drawing shows the minimum amount of measurement of the drawing size, so don't make actual measurement of the drawing shape.



| |
|----------------------|
| Japan |
| Foreign countries |
| () |
| () |
| Not yet decided |
| () |
| () |
| Number of mold drive |
| Weight |
| Approval |
| Drawing inspection |
| Designing |
| Working-out drawing |
| Copying of drawing |
| Filing of drawing |
| Our used early model |
| Temporality name |

| | | | |
|--------------------|------------|------------|------------------|
| Material dimension | © () | 6002 A | (8/10) |
| Processing | Ⓢ () | CPU | () |
| Size tolerance | Ⓐ () | | () |
| 1000 ± | | | |
| 300-1000 ± | | | |
| 100-300 ± | Sym bol | Date | Content revision |
| 100 ± | Parts name | Parts cord | |
| Scale | Quantity | | |
| Unit no | | | |

